D6033

§493.1409 Condition: Laboratories **p**erforming **m**oderate **c**omplexity **t**esting; **t**echnical **c**onsultant

The laboratory must have a technical consultant who meets the qualification requirements of §493.1411 of this subpart and provides technical oversight in accordance with §493.1413 of this subpart.

Interpretive Guidelines §493.1409

The Condition of technical consultant is not met when the technical consultant:

- Position is not filled;

- Is not qualified; or

- Does not fulfill the technical consultant's responsibilities.